

## TEST REPORT

Report No.: HL60521/2020 Page: 1 of

Date: JUL. 07, 2020

## DE LAI PLASTIC CO., LTD.

NO. 2, LN. 96, XINGXONG RD., XIANXI TOWNGSHIP, CHANGHUA COUNTY507, TAIWAN

The following merchandise was submitted and identified by the applicant as:

SAFETY CHAIN W/PLASTIC HOSE Product Description:

Style/Item No.: A110 **Country of Origin: TAIWAN** 

We have tested the submitted sample as requested and the following results were obtained:

Test Requested: Pulling test

Test Method: 1. Secure the sample on the testing machine. (See photo B)

2. Apply an increasing upward force to the sample until it is damaged or up to

4,900 kgf.

3. Record the max. force and any findings.

4. Testing Machine: INSTRON 5581, Rate: 10 mm/min.

Test Result:

Sample	Max. force (kgf)	Remark
SAFETY CHAIN W/PLASTIC HOSE	104	The sample was damaged after testing. (Photo C)

Date of Receipt: Jun. 30, 2020

**Testing Period:** Jun. 30, 2020 ~ Jul. 07, 2020

Note: The content of this report is invalid if it is not presented as the entire report.

- Picture(s) Signed for and on be

Sturm Su Asst. Manager

This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sqs.com.tw/Terms-and-Conditions and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at http://www.sgs.com.tw/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of client's instruction, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced, except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful



## **TEST REPORT**

Report No.: HL60521/2020

Page: of






Photo A: Appearance of the sample

Photo B: Test setup



Photo C: After testing

---End of Report---

This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <a href="http://www.sgs.com.tw/Terms-and-Conditions">http://www.sgs.com.tw/Terms-and-Conditions</a> and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at <a href="http://www.sgs.com.tw/Terms-and-Conditions">http://www.sgs.com.tw/Terms-and-Conditions</a>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of client's instruction, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced, except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.

\*\*SGS Taiwan Ltd.\*\*

\*\*SGS Taiwan Ltd.\*\*

\*\*No.127\*

\*\*We Kung Road, New Taipei Industrial Park, New Taipei City, Taiwan / 新北市新北產業園區五工路 127 號t (886-2) 2299-3279

\*\*Taiwan / Jaiwan /