

ROCK Red

Test Report

No. : CY/2007/C1381 Date : 2008/01/04 Page : 1 of 3

M&S INTERNATIONAL CO., LTD
60 MARKET SQUARE, P.O. BOX 364, BELIZE CITY, BELIZE, CENTRAL
AMERICA



The following sample(s) was/were submitted and identified by/on behalf of the client as :

Sample Description	:	PLASTIC CLIMBING ROCK HOLD-RED
Style/Item No.	:	IFP-148 RED
Manufacturer/Vendor	:	DE LAI PLASTIC CO., LTD.
Country of Origin	:	TAIWAN
Sample Receiving Date	:	2007/12/26
Testing Period	:	2007/12/26 TO 2008/01/04

Test Result(s) : Please refer to next page(s).

James Lu
 James Lu / Supervisor
 Signed for and on behalf of
 SGS TAIWAN I.TD.
 Chemical Laboratory – Taipei

The test report is issued on the basis of the sample submitted to the Client Laboratory of Service (please refer to available on request and accessible at www.sgs.com), which may be used for internal and external purposes, without prior written permission of the issuing lab. Any unauthorized circulation, modification, or use of the report is prohibited and offenders may be prosecuted to the fullest extent of the law.

6511501

1/1/08

Test Report

No : CY/2007/C1381

Date : 2008/01/04

Page : 2 of 3

MRS. INTERNATIONAL CO., LTD
60 MARKET SQUARE, P.O. BOX 364, BELIZE CITY, BELIZE, CENTRAL
AMERICA



Test Result(s)

PART NAME NO 1 : RED PLASTIC

PASS

Test Item (s):	Unit	Method	MDL	Result	Limit
				No.1	
Lead (Pb)	mg/kg	As per U.S.A. standard of Part 1303, Title 16, Code of Federal Regulation (CPSC)	2	n.d	600

- Note :
1. mg/kg = ppm
 2. n.d = Not Detected
 3. MDL = Method Detection Limit

6011692

Test Report

No : CY/2007/C1381


Date : 2008/01/04

Page : 3 of 3

M&S INTERNATIONAL CO., LTD
80 MARKET SQUARE, P.O. BOX 364, BELIZE CITY, BELIZE, CENTRAL
AMERICA



CY / 2007 / C1381



^^ End of Report ^^

0011603