

TEST REPORT

No.: SUIN1807006515ML

Date: Jul 30, 2018

Page: 1 of 3

CUSTOMER NAME:

LEADER HARDWARE(KUNSAN)CO.,LTD

ADDRESS:

9327 WHEATLANDS RD SANTEE CA 92071

Sample Name

3-1/2"PIPE HANGER- DUCTILE IRON

Product Specification

SH125

Product or Lot No.

PO#17831stk cn

Manufacturer

LEADER HARDWARE(KUN SHAN) CO., LTD.

Buyer

: JENSEN SWING PRODUCTS

Material and Mark

STEEL

Above information and sample(s) was/were submitted and confirmed by the client. SGS, however, assumes no responsibility to verify the accuracy, adequacy and completeness of the sample information provided by client.

Test Required

: Tensile Test

Date of Receipt

: Jul 23, 2018

Testing Start Date

Jul 23, 2018

Testing End Date

: Jul 30, 2018

Test result(s)

For further details, please refer to the following page(s)

(Unless otherwise stated the results shown in this test report refer only to

the sample(s) tested)

Signed for

SGS-CSTC Standards Technical Services Co., Ltd. Suzhou Branch

Trista li

Authorized signatory





TEST REPORT

No. : SUIN1807006515ML

Date: Jul 30, 2018

Page: 2 of 3

Tensile Test:

Test Method: Per client's requirement

Step 1. Fix the sample on the test equipment, please see the test photos;

Step 2. Drawing at the certain rate until the sample was broken;

Step 3. Check the location of fracture and record the force.

Test Result(s):

Sample	Broken force (lbf)	Location of fracture
1#	6004.9	See photos



TEST REPORT

No.: SUIN1807006515ML

Date: Jul 30, 2018

Page: 3 of 3

Testing Photos:





Original sample



Before test



After test

During test The test was performed by SGS other internal laboratory.

- The test report was published by SGS-CSTC SuZhou Branch.
- Part/all of the test methods are not in CMA accredited scope, the test report shall only be used for client scientific research, teaching, internal quality control, product research and development, etc. and just for client internal reference.

******* End of report******

